



Visor Post for Helmet – 2 required per Helmet

Variant code: 22-FXVP30

Posts for fixing the carrier to a Scott Protector helmet, without ear defenders. 2 per helmet required.